

September 25, 2017

MC-124
Mr. Chance Goodin, Manager
MSW Permits Section
Office of Waste, Waste Permits Division
Texas Commission on Environmental Quality
P. O. Box 13087
Austin, TX 78711-3087

**Re: Addendum to July 12, 2017 Verification Resampling Report for
Blue Ridge Landfill
MSW Permit No. 1505A
Fort Bend County, Texas
RN102610102; CN600343826**

Dear Mr. Goodin:

MW-1-3S had previously reported concentrations of benzene associated with an October 2014 monitoring event. Since that time neither benzene nor any other VOC has been reported for MW-1-3S. Statistical evaluation and historical review of data collected for MW-1-3S reveals no corroborating indication of impact from waste disposal activities. As the well shows no impact from waste disposal activities we request that MW-1-3S be allowed to return to detection monitoring status in accordance with 30 TAC §330.409(e).

If you have any questions about this information, please contact me at (936) 568-9451.

Sincerely,
Hydrex Environmental
TBPG Firm No. 50027



Leonell N. Scarborough, P.G.
Senior Hydrogeologist

Distribution:

- (Email + Original + 1) Mr. Chance Goodin, Manager
MC-124
MSW Permits Section
Waste Permits Division
Texas Commission on Environmental Quality
P. O. Box 13087
Austin, TX 78711-3087
- (1) Ms. Ashley K. Wadick
Regional Director
TCEQ Regional Office 12
5425 Polk Ave., Ste. H
Houston, TX 77023-1452
- (1) Mr. Burgess Stengl
Environmental Manager
Republic Services, Inc.
P.O. Box 879
Fresno, TX 77545
- (1) Mr. Eric Ballenger
Manager Hydrogeology
Republic Services, Inc.
E-copy
- (1) Mr. Matthew Montagna
Operations Manager
Blue Ridge Landfill
P.O. Box 879
Fresno, TX 77545
- (1) Mr. Eric Wilson
Director of Public Works
City of Pearland
3501 East Orange Street
Pearland, Texas 77581
- (1) Hydrex Environmental
E-copy